



GUI5

Ultrasonic Prototype System

Configuration Graph Analysis

GUI5

Archivo

Atr

Dirección

Ultrasonic Prototype System

Configuration Graph Analysis

Ultrasonic Burst Emission:

Frequency (in Hz)

0

Number of pulses

0

Send Ultrasonic Burst Configuration

Acquisition Parameter Configuration :

Number of Points at 2,4MHz Sampling freq.

0

Delay Time Before Acquisition (in ms)

0

Send Acquisition Parameter Configuration

Filter Parameters :

b00

0,0000

b01

0,0000

b02

0,0000

Send Filter Parameters

Ultrasonic board connection:

Serial COM Port connection

28

Baud Rate

115200

Ultrasonic Measurements :

☐ Manual

☒ Automatic

1

Start Ultrasonic Measurement

Stop Ultrasonic Measurement

WINDOWS\system32\cmd.exe - GUI5.py

1391941  
0047619  
1978022  
021978  
021978  
0805861  
06337  
021978  
0805861  
021978  
06337  
1391941  
06337  
tic mode  
et data!  
son los datos 3450;3448;3449;3448;  
3447;3447;3449;3446;3447;3448;  
1978022  
0805861  
1391941  
0805861  
3736264  
021978  
1391941  
021978  
021978  
0805861  
021978  
06337  
021978  
021978  
021978  
1391941  
06337  
021978  
021978  
0805861  
tic mode

Notepad++